


QUALCOMM Incorporated Page 2 of 4 010110; EV 074 585 551 US Rotem Cooper METHOD AND APPARATUS FOR EFFICIENT... TRANSCEIVER 84 98 LOOKUP TABLE 106 PROCESSOR SEARCHER 94 SIGNAL 92 AVOIDANCE 104 DATA PROCESSING CIRCUITRY MEMORY PROCESSOR CONTROL 90 ACQUISITION TABLE 102 *80* ~ **DETERMINATION** SYSTEMS CLOCK 100 TABLE SYSTEM UNIT ~ *86* 82 -96

QUALCOMM Incorporated Page 3 of 4 010110; EV 074 585 551 US Rotem Cooper

METHOD AND APPARATUS FOR EFFICIENT...



QUALCOMM Incorporated Page 4 of 4 010110; EV 074 585 551 US

Rotem Cooper

METHOD AND APPARATUS FOR EFFICIENT...

AVOIDANCE_DURATION
30 seconds
30 seconds
2 minutes
2 minute
5 minute
1 minute

Registration Rejected By Wireless Communications System

Unable to Acquire Synchronization Channel

204

202

206

Unable to Acquire Pilot Signal

Unable to Acquire Paging Channel

Mobile Station Has Experienced Frequent Signal Fading

210

208

Invalid Redirection

214

212

Protocol Mismatch

ACQUISITION/REGISTRATION FAILURE

	C	
(1	7
Ì	Ī	